






- NOTES
- 1- ALL RESISTORS 1/2W 5% UNLESS OTHERWISE SPECIFIED.
 - 2- R1 THRU R6, FRONT PANEL MOUNTED POTENTIOMETERS ARE NOT SHOWN, REFER TO A-T DWG # 2F8094
 - 3- REFERENCE DRAWINGS:
A- ARTWORK 2F8064
B- FAB DETAILS 2F8074
C- ASSEMBLY 2F8084
D- SYSTEM WIRING DIAGRAM 2F8094
 - 4- R87, & R89 ARE OMITTED AND REPLACED WITH JUMPERS E2, & E4



REVISIONS		2F8034	
REV.	DESCRIPTION	DATE	BY
1	CHANGED R18 WERE 10K TO 100K, CHANGED R3478 WERE 100K & R3479 WERE 50K	7-15-70	DJA
2	CHANGED R18 WERE 10K TO 100K, CHANGED R3478 WERE 100K & R3479 WERE 50K	7-15-70	DJA
3	CHANGED R18 WERE 10K TO 100K, CHANGED R3478 WERE 100K & R3479 WERE 50K	7-15-70	DJA
4	CHANGED R18 WERE 10K TO 100K, CHANGED R3478 WERE 100K & R3479 WERE 50K	7-15-70	DJA
5	CHANGED R18 WERE 10K TO 100K, CHANGED R3478 WERE 100K & R3479 WERE 50K	7-15-70	DJA
6	CHANGED R18 WERE 10K TO 100K, CHANGED R3478 WERE 100K & R3479 WERE 50K	7-15-70	DJA
7	CHANGED R18 WERE 10K TO 100K, CHANGED R3478 WERE 100K & R3479 WERE 50K	7-15-70	DJA
8	CHANGED R18 WERE 10K TO 100K, CHANGED R3478 WERE 100K & R3479 WERE 50K	7-15-70	DJA
9	CHANGED R18 WERE 10K TO 100K, CHANGED R3478 WERE 100K & R3479 WERE 50K	7-15-70	DJA
10	CHANGED R18 WERE 10K TO 100K, CHANGED R3478 WERE 100K & R3479 WERE 50K	7-15-70	DJA